

GENERAL REMARKS

(State quality of workmanship, opinions as to class, &c.)

The donkey boiler of this vessel was constructed under special survey of material tested to Rule Requirements and workmanship was good throughout.

[Faint, mirrored text from the reverse side of the page is visible through the paper, including words like 'VERTICAL DONKEY BOILER', 'Description of boiler', 'plates', 'Top 6 3/4" x 8"', 'smallest part', 'Pitch of st', 'Area supp', 'Lower back', 'Pitch of tw', 'water spac', 'girder at c', 'Working p', 'Diameter', 'Pitch of riv', 'Date of Test', 'Diameter of', 'Made at', 'tested by hy', 'No. of safety', 'enter the do', 'strength', 'Lap of plat', 'Radius of d', 'Thickness of', 'plates', 'Thickness of']

Certificate (if required) to be sent to
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

The amount of Entry Fee .. £	:	:	When applied for,
Special £	:	:19.....
Donkey Boiler Fee £	:	:	When received,
Travelling Expenses (if any) £	:	:19.....

Committee's Minute

Assigned

New York NOV 23 1920
See S. F. Rpt. No 3394

A. W. Lawson
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2021
Lloyd's Register
Foundation

pt. 5.
No. in S
Reg. Book.
on
aster
Engines ma
Boilers mad
Registered
MULTIT
Letter for
Boilers 3
Nos of Cert
safety valve
Are they fit
Smallest di
Material of
Descrip. of
Lap of pla
rules 24
boiler 3 1
Description
plates: Mo
Top 6 3/4" x 8
smallest pa
Pitch of st
Area supp
Lower back
Pitch of tw
water spac
girder at c
Working p
Diameter
Pitch of riv
SUPERH
Date of Test
Diameter of
VERTIC
Made at
tested by hy
No. of safety
enter the do
strength
Lap of plat
Radius of d
Thickness of
plates
Thickness of
Dates
of Survey
while
building