

at to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME STEEL DUCHESS OF RICHMOND Report Sl No. 48696**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." — Extract from Sub-Committee's Report, 24/5/82.)

Nature of Survey 1st Entry When due Revised Rule

✠ 100 A.1. (Steel). With Heelboard.

H D^{ks} (Stl - weather D^k pt w.s.), 5⁴ D^k (Stl) in No 2.5.7 holds
Cell D.B. 510' 2547t, D.T. 43 700t, Tanks in way of tunnels 474t, F.P.T. 193t APT 269t
F.K. 11 B.H (Coll B.H to weather D^k). pt Cen, Lloyd's A.C.P.
B.F. 520'
Promenade 325'

It is concluded the riveting of the ~~bottom~~ ^{bottom} of the shell side and topside plating
is as approved but the ~~surveyors~~ ^{surveyors} should be requested to state if this is so
Dr. 29/12/28