

TWIN S.S. "HEROIC".

Belfast No. 7082.

*"Graphic"*

7093

This vessel and her machinery were built in 1906 by Messrs. Harland & Wolff, but not under the survey of the Society's Surveyors.

The engines and boilers have now been surveyed by the Belfast Surveyors with a view to classification and are reported to be in good order and condition.

The screw shafts have been examined as far as possible without drawing in the shafts and found satisfactory. The Owners request that the complete examination of these shafts may be postponed until the overhaul in twelve months' time. They point out that these shafts are not fitted with liners and run in oil, and were <sup>drawn in</sup> examined and passed by the Board of Trade Surveyors in April and May last year. It might be noted that they are  $1\frac{1}{4}$ " larger in diameter than required by the Rules.

It is submitted that in the circumstances, the Owners' request might be approved, and that the record of LMC 5-12 ~~might~~ be assigned in this case, on the understanding that the screw shafts will be drawn in for examination next year.

(al.)

21.5.12

JVRJL

21.5.12.



© 2021

Lloyd's Register  
Foundation

W1627-0093

26.12.