

11- JAN 1953

Received from Chief Ship Surveyor

S NAME "CALEDONIA" REPORT Gal. No. 15338

Standing Conditions of Class:

Subject to forecastle sheerstrake plate No.2 (p.s.) being dealt with at the Special Survey, to 60 fathoms of chain cable and a bower anchor being supplied and a bower anchor and 75 fathoms of chain cable (supplied Cbo.6,52) being tested at the earliest opportunity.

ACTION is DEFERRED for Equipment.

Assessment of Class (B) (~~As before~~ or None)

Result of Present Survey: (Afloat and in dry dock) Damage (collision), temporary repairs.

Recommendation: SUBJECT as above, and to permanent repairs to set in bulwark plating, etc. (p.s.a.) by next Special Survey, but further ACTION continue to be DEFERRED for Equipment.

As Now. Subject.



© 2021

Lloyd's Register
Foundation

W1628-0204