

So far as pumping arrangements are concerned there should be no connection between the ships oil fuel system and the cargo tank lines.

If there are any connections from the cargo tank lines to the forward or after deck cofferdams these should be removed.



© 2021

Lloyd's Register
Foundation

W1629-0128