

7-367 1062

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "DALEBY" REPORT Nwc. No. 100729

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

(1st S.S. No.3 due 11.41.)

The class is subject to indented keel and bottom plating & shell plate F5 (p.s.) and bulkhead in way being repaired; to repairs to bulkhead boundary angle (leakage) ~~between~~ between Holds Nos. 1 and 2 at the first opportunity, ~~and~~ to indented & hold shell plating in way of No.2 hold (P. and S.) at the first opportunity, and to deck stringer plate in tween deck bunkers (s.s.) locally holed being renewed on return to the U.K. (and to 45 fathoms of chain cable being supplied).

The NEWCASTLE Surveyors now report the vessel placed on Pontoon, bottom coated, a general examination held and repairs effected to decks and framing and tween deck bunkers, as above. *Explosion* etc. The bulkhead boundary angle as above has now been permanently dealt with. A tunnel escape has been supplied.

(1) A bower anchor and 30 fathoms of chain cable have been supplied, to replace equipment lost. The bower anchor is stated to have been lost previously and it is recommended by the Surveyors to be made good at the earliest opportunity.

The other outstanding items as above, examined and found efficient.

Extension of W.T.B.Hs.

Four tween deck bulkheads have now been fitted (see report 10 and sketch attached) and the work is complete.

It is submitted that the vessel is worthy to remain as classed, with record of docking survey 9.42, as recommended (1) and as above except as regards bulkhead boundary angle and stringer plates in tween deck bunkers, and that a notation "Examined 9.42 valid for 12 months as recommended" be assigned.

As now
9.42 *Shl* Shields

Subject, etc. }
Without, etc. }

Examined 9.42.

T. O. CLOSED. (W.E.)



© 2019
Lloyd's Register
Foundation

W163-0035