

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 9. 12. 1952. When handed in at Local Office 10 DEC 1952. Port of GRIMSBY.

No. in Reg. Book 74556 Survey held at GRIMSBY. Date, First Survey and Last Survey 25. 11. 1952. (No. of Visits One)

on the ~~Wood, Iron or Steel~~ Steam Trawler "RIVIERE" Built at Beverley By whom Cook, Welton & Gemmell, Ltd When 1916 5

Managers Grimsby Industries (Trawler Managers) Ltd. Owners' Address - (If not already recorded in Appendix to Register Book). Port belonging to Grimsby.

Surveyed Afloat or in Dry Dock? Slipway. Name of Dock Fish Dock. Destined Voyage Fishing.

Cell DBor DBa feet; uE & B feet; f feet fee total capacity tons FPT tons; APT tons; MT feet tons. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER: * for Special Survey Date of last Survey and of Periodical Surveys. Machinery and Boiler Surveys (Including date of N.B., if any).

100AL Stm. IMC 4,49. Trawler 5,52. BS 6,51. TS.CL. 6,51. s.s.Gms. 2nd.No. 3- 7,44. s.s.Gms. 4,49.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

REPAIRS, OR EXAMINATION AS PER RULE, FOR DOCKING.

NOW DONE: Vessel placed on slipway. Bottom, keel and rudder examined, found in good order and recoated.

Table with columns: Shell Plates, Frames, R. Frames, Floors and Bracket Floors, Beams, Inner Bottom Plates, Dk. Plates, Other Items :-

Table with columns: Decks, Bulkheads, Engine Room Skylights, Copper, or Y.M., Caulking of Decks, Ceiling, Coal Bunkers, Openings, Covers, &c., When fitted, Month, Year, Coamings, Cement or Asphalt, Oil Bunkers, Scuppers, Boats, Beams & Fastenings, Rudder, Cargo Hatchways, Masts, Yards, &c., Outside Plating, Steering gear and its connections, Hatches, Condition, how ascertained, Frames, Windlass, Have pumps been examined and found efficient?, Planking, Caulking, Equipment letter, Reverse Frames, Have Sluice Valves been examined and found efficient?, Treenails, Anchors, No. of, Longitudinals, Have Watertight Doors been examined and found efficient?, Breasthooks & Stemson, Transoms, Pointers & Crutches, Transverses, Have Ventilators and their Coamings been examined and found efficient?, Timbers of Frame at openings, " " at other places, Chains, length, mean diamr., (on board.), Rule length, size, Floors, Keels, Stringers, Inner Bottom Plating, Have the Tanks been examined internally?, Have the Tanks been tested?, Doubling Plates under Sounding Pipes, Salting, Sails

General Observations, Opinion as to Class, Recommendation, &c. :- State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: - "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

The vessel is in a good and efficient condition and eligible, in my opinion, to remain as classed with fresh record of Docking 11,52.

Survey Fee (per Section 29) £ : : Fees applied for, Special Damage or Repair Fee (if any) (per Sec. 29) £ : : Received by me, Travelling Expenses (if chargeable) £ : : Second Surveyor's Fee (if any) £ : :

Committee's Minute THU 18 DEC 1952 Character Assigned 11.52 Gms BS 12.52 without opl cdn(m)



Has a Survey also been held on the Machinery of the Ship? If so, is the Report sent now, or when will it be sent?

20m. 345. Transfer Ink. (MADE AND PRINTED IN ENGLAND.) (The Surveyor is requested not to write on or below the space for Committee's Minutes.)

W 1634-0001