

"REYKJANES"

Hul. 54243.

IT IS SUBMITTED the Hull Surveyors be referred to Secretary's letter of the 3rd June and be asked to state particulars of the size and position of the bilge injection and the direct bilge suction to the ballast pump. This information has been omitted from their First Entry report and is desired so that the case can receive attention.

Enc.



© 2021

7. 8. 47.

Lloyd's Register
Foundation

W1634-0058