



Lloyd's Register of Shipping,

Lloyd's Bank Chambers,

Middlesbrough, 26th August 1936.



Dear Sir,

In reply to the query in your classing letter of 25th instant respecting Middlesbrough Report No.15773 on steam trawler "INDIAN STAR" we have to confirm that there are no fuses fitted on the live side of the switches.

We have asked the Builders for the dynamo test certificate and it will be forwarded in a day or two.

We are, Dear Sir,

Yours faithfully,

The Surveyors,

Per:-

The Secretary,
LONDON.



© 2021

Lloyd's Register
Foundation

LONDON.

The Secretary.

27 AUG 1936

*Noted
Mun*

also for Mr. Spinks to note.

Ref:-

The Surveyors.

Yours faithfully,

W. E. G. G. G.

CWO

best certified and it will be followed in a day or

We have asked the Engineer for the day

of the engine.

confirm that there are no more letters on the line and

NO. 1000 on a new engine. "INDIAN 2000". We have

letter of 1000 in the engine room and the engine

in the day to the day in the engine

Ref:-



© 2021

Lloyd's Register
Foundation

seth vander 1838.

Lloyd's Bank Company

London and the City