

Received from Chief Ship Surveyor 24 MAR 1953

SHIP'S NAME Esso LA MAILLERAYE

REPORT Southampton

No. 21629

Outstanding Conditions of Class: Subject to indented shell plating etc. in way of oil fuel bunkers (s.s.) being dealt with by the next Special Survey, and to permanent repairs to the ship's side plating etc in the forward inter tank (s.s.) by the next dry-docking

Endorsement of Class (B) (As before ~~or None~~)

Nature of Present Survey: (Afloat and ~~in dry dock~~)

Examination of damage caused by collision

Recommendation: Subject as above, and to rising shell plate at aft end of side (p.s.) etc. being repaired as necessary at next dry-docking

be now subject

Endorsement of Class (B)
Indented in shell plating (p.s.)



© 2021

Lloyd's Register
Foundation

EL.
20.3.53

W1636-0205