

2

s

26th March, 1954.

Two


s are

BOMBAY

ALAVI". 10902. As recommended.

10889. "JALADURGA". As recommended. I would, however, draw your attention to the fact that in July last, the Madras Surveyor recommended that the piston rods of the windlass and port inner dynamo engines and steam cylinder of the forward feed pump should be specially examined, the top halves of Nos. 1, 4, 5 and 6 main bearings remetalled and the air pump barrel of the port main engine renewed before the end of December. It is concluded these items have, in fact, been dealt with, but I shall be glad to receive your confirmation on this point, in view of the fact that your report makes no reference to S.R.L. items.

10903, 05, 06. As recommended.



Lloyd's Register  
Foundation