

TSS. "LAGUNILLA" (continued)

ck beams 1 to 20 in No. 2 ballast tank.
ck beams 4 to 18 in No. 3 air space.
tboard beam knees 1 to 20 in No. 2 ballast tank.
tboard beam knees 4 to 18 in No. 3 air spcae.
part renew approximately 8 square feet.
gusset bracket.
tboard of bulkhead plate also boundary bar in way.
nety feet of harbour deck twin handrails and stanchions.

not done at this time, pending prospective purchasers' decision, regarding
of vessel.

urveyed in view of issuing Seaworthy Certificate for passage from Aruba to
where repairs were intended to be carried out.

W. D. Wardle



© 2021

Lloyd's Register
Foundation

W 638-0200