

COPY.

27 AUG 1953

Lloyd's Register of Shipping.

COPY FOR LONDON OFFICE No. 5963



Port Wellington, N.Z.

5th. March, 1953.

This is to Certify that

W. KIMBER & C. WALLIS

the undersigned Surveyor to this Society did at the request of the Owners, MESSRS THE SHAW SAVILL AND ALBION CO. LTD., Wellington attend on board the S.S. "MAHIA" 8822 tons gross of Southampton on the 2nd. March, 1953 and subsequently as the vessel lay afloat at Wellington for the purpose of ascertaining the nature and extent of the damage stated to have been caused when discharging cargo. It was stated that a boiler dropped onto the deck of the "Mahia" from a height of approximately ten feet.

For further particulars please see vessel's log books.

UPON EXAMINATION FOUND

Starb. side abreast of No. 2 Hatch indented, maximum 3", area affected 12ft. x 4 ft.

Four deck beams Nos. 139, 140, 141 and 142 buckled.

Thermometer pipe deck fitting and pad broken away from deck plating.

Five off refrigerated hatch beams buckled in various places.

One section of portable hand rail (Starb. Side) buckled and broken.

All new and disturbed work to be replaced in good order and given two coats of approved paint.

The above recommendations have been made with a view to placing the vessel in the same efficient condition as before the damage was sustained.

RECOMMENDED

Two plates to crop, part renewed and hose tested upon completion of repairs.

To remove, fair, refit and hose test upon completion of repairs.

To be part renewed and refitted to deck. (Completed at Wellington).

To be completely stripped, faired, parts renewed as necessary and all hatch plugs to be refitted between beams.

To be faired, rewelded and refitted.

SURVEYOR TO LLOYD'S REGISTER

W. Kimber & C. Wallis

L.O.O.
16.0

This certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."