

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19. When handed in at Local Office 7. 9. 12. Port of Glasgow.
 No. in Reg. Book. Survey held at Glasgow. Date, First Survey 7th August 1912 Last Survey 4. 9. 1912.
 on the Wood, Iron or Steel S.S. "Wheatlands" (No. of Visits) 5 Master ✓
 TONNAGE:— Built at Dublin By whom Dublin Dockyard Co. When 1912 MONTH.
 GROSS 873 Owners Spillers & Bakers Ltd Port belonging to Cardiff
 UNDER DK. 873 Owners' Address
 NET (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Yes Name of Dock Quinces Dock Destined Voyage

WB=Cell DBor DBa feet; u.E&B feet; f feet; }
 total capacity tons. FPT tons; APT tons; MT feet tons. }

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey, Date of last Survey and of Periodical Surveys	Years Assigned now required	Machinery and Boiler Surveys (including date of N.B., if any).
+100 A.I. (Contemplated)		

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

Now done Engine & Boiler casing satisfactory, painted up after shipment of Machinery.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt.)
Decks	Inner Bottom Plating	Engine Room Skylights	When put on, Month Year
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Oil Tanks, Lids, &c.	Boats
Waterways	State if Tanks now tested	Scuppers	Masts, Yards, &c.
Coamings	Bulkheads	Cargo Hatchways	Condition, how ascertained
Beams & Fastenings	Ceiling	Hatches	(State if wedges removed)
Outside Plating	Cement or Asphalt (State which.)	Planking of Wood Vessels	Sails
Caulking of ditto	Rudder	Caulking ditto	Equipment letter
Rivets	Steering gear and its connections	Treenails ditto	Anchor, No. of
Breasthooks & Crutches	Windlass	Breasthooks & Stemson ditto	Cables (State if now ranged)
Transoms	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto length .. size (on board)
Frames	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto Rule length .. size
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	Hawser & Warps
Floors		Stringers, Clamps & Shells ditto	Standing & Running Rigging
Keelsons		Salting ditto	
		(State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,10," or "to remain as classed and to have record of survey, 1,10, and the notations of ss No. 1-10 and ptND10, &c."

The above report is forwarded for the information of the Committee

Survey Fee (per Section 98)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 98)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character Assigned

GLASGOW

17 SEP. 1912

Transmit to London

FRI. SEP. 20 1912

© 2020

Lloyd's Register Foundation

W1641-0044

N.B. - If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN

is a Report also sent on the Hall of the Shee.

if not, state whether, and when, one will be sent?

co
N
N
N
In
No
Ar
Ar
Ar

OI
Tota
Wor
Zan
ach

hick
ing.
er c
ize o
engt

aters
aters
are
met
ickne
mete

knes
 r kin
 rated
 ffen

10

When Anchors or Cables are supplied, the particulars are to be reported in the following form:

ANCHORS.

ANCHORS.

Number of Certificate.	Anchors.*	WEIGHT, EX. STOCK.			WEIGHT OF STOCK.			TEST, PER CERTIFICATE.			WEIGHT REQUIRED by TABLE 30 or 31.			Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons.	Cwts.	qrs.	lbs.	Cwts.	qrs.			
	1st Bower ...															
	2nd "															
	3rd "															
	Collective Weight.															
	Stream															
	Kedge.....															

* If Patent state name of Patentee.

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

[illegible]