



Port

KARACHT

147
IN 142

2 DEC 1952

Received from Chief Ship Surveyor

NAME "YORBA LINDA" REPORT Krh. No. 1998

ding Conditions of Class: Subject to 45 fathoms of chain cable (supplied Kob.3,52) being verified at the earliest opportunity and to permanent repairs to wasted shell plates A.1 (p & s) from aft by 4,53.

ACTION is DEFERRED for completion of the Special Survey (Machinery).

ement of Class (B) (~~As before or~~ None)

of Present Survey: (~~Afloat and in dry dock~~) Repairs to windlass.

ondation: SUBJECT as above, and to repairs to windlass being examined by 5,53.

As Now. Subject.



© 2002

Lloyd's Register Foundation

W1641-0099

Handwritten: J.M. 28.11.52

Cables (State if no

length