

W1641-0118

sp. "Tolly Bridge"

Nwc. 68725

It is submitted the Newcastle Surveyors should be informed it is concluded that the blow-off cocks are fitted with spigots & brass covering plates, but as this is not stated on their report they should confirm it.

They should also be informed that the nominal H.P. by the Rules is $\frac{7}{4}$ not 50 as stated in the report. The fee should be amended accordingly.

