

Gross Tonnage
Less Crew Space
Less other spaces of

4021.46
134.61

Longitudinal Number
Depth "d" at middle of length. See Secs. 2 & 13.

Owners
Managers
W. O. B.

Aina Maria Humunen

1

Sent to Chief Surveyors

5/6/12

Received from Chief Surveyors

VESSEL'S NAME

H. H. Kirkosmala

Report

Elo

No.

3/509

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Nature of Survey

First entry

When due

+ 100A1 (Stub) Shutter deck with foreboard
1/8" (old) + Web frames, Shutter on (du) 2nd str (sq) in
No 1 hold, longitudinal framing
NB. but DBa 109' u 3 + 13 3/4' f 16' 10 7/16' EPT 130' EPT 224' 6"
FR GBH Gen. Lloyd at 60.

M
RIB
6/6/12



© 2020

Lloyd's Register
W16A2 - 0064
Foundation

Angles on upper edge

Spacing

Loop Deck Stringer plate, breadth & thickness

Angles on ditto

Tie Plates