

"GUELDER ROSE"

Rweideter

NN - aRenside

It is submitted the Newcastle Surveyors in reply to their telephonic enquiry be advised by 'phone as follows:-

Original Midship Shell thicknesses:-

Raised Quarter Deck sheerstrake: .42" + .14" at break.

Upper Deck Sheerstrake from $\frac{1}{2}$ L forward to 16 frame spaces abaft after end of bridge .78"

" " " 1. way of Raised Quarter Deck .44"

Strake below Upper Deck Sheerstrake in way of Upper Deck .46"

" " " " " " " " Raised Quarter Deck .42"

2nd strake below Upper Deck Sheerstrake .42"

3rd " " " " " .38"



2020
24.8.43.

Above phoned hwe 24/8/43

Lloyd's Register
Foundation
W1642 - 0259

This FE and midship section, now to be sent here.
Survey fee (634 x 0.60) 380.40

Travelling expenses if any

31.14.0

ALL
THE

om built N.V. Sch...
"de Merwe...
ng In...
Piles