

23 JUL 1954

4E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

"ATHELPRINCE"

REPORT

Drb

No 6479

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

~~REPAIRS TO ENGINES AND BOILERS DUE TO~~ DAMAGE THROUGH HEAVY WEATHER

Starboard main engine sea water cooling pump cover found cracked temporarily repaired and the Surveyor recommends this cover be renewed on the vessel's return to the UK.

IT IS SUBMITTED the vessel is eligible to remain as classed, subject as recommended.



© 2021

22.7.54.

Lloyd's Register
Foundation