

W1643-0218

Im.10.33.

Received by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME "OJEDA"

Rpt. *Rat.* No. 26504


The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey \_\_\_\_\_

*It is submitted before this case receives the consideration of the Committee, the Surveyors should be informed it is concluded the bottom of the vessel in way of the engine & boiler space has been coated with cement or other approved composition as required by Section 32 of the Rules, but they should state if this is so.*

*(Bottom in way of E. & B. space coated with Bitumastic enamel (see Rot Lt. 23/2/38)*

*J.W.*  
*18. 2. 38*  


© 2021

Lloyd's Register  
Foundation