

5c.12.24

*Fees Paid.*

F.E.  
(FBD.)

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Single Sc. Steamer "BECKENHAM" Rpt. Dun. No. 9007  
Nwc. 95550

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No.	14760	Depth "d"	24.4
2nd Long. No.	37925	Proportions = $\frac{L}{D}$	11.08
Framing Bulb angle frames as approved	Sheerstrake	As approved	

The Newcastle Surveyors report the ship placed in dry dock, the bottom cleaned and coated.

*This is a sister ship to the "BLACKHEATH"*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ~~100A~~ "With Freeboard"

The Summer Freeboard as shown on the attached extract from the Freeboard Verification Form, now marked on the vessel's sides, to be inserted in the classification certificate and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying extract, to be inserted in the certificate of classification.

- 1 Dk. and Shelter Dk.
- Cell. DB 345' 1035t, FPT 267t, APT 190t.
- FK, 7BH (Coll. BH to Shelter Dk., 6BH to 2nd Dk.), Asp., Lloyd's A & CP.



*Handwritten initials and date: 10.37*

Lloyd's Register  
Foundation  
W1644 - 0163

Handwritten signature or initials in blue ink.



© 2020

Lloyd's Register  
Foundation

DOUB

SUN

form

LLOYD'S REGISTER

GRAMS

R

Res