

23 NOV 1944

Port of GLASGOW.

5th October, 1944.

REPORT ON MASTS, SPARS, AND RIGGING.

Sirs,

Having, in accordance with your instructions, examined the Masts, Spars, and Rigging, and Iron Work of same, of the s/s "BRITISH COURAGE"

I have to report that I found Main Rigging:- Port shrouds bad, should be renewed. Starboard shrouds require cleaning, reserving, and reseizing. Topmast Stay and Topmast Backstays bad, should be renewed.

Fore Rigging:- In good condition. Clean, reserve and reseize where required.

Yours faithfully,

A. M. 'Shenji

Fee £ 1. 0. 0.

to the Surveyors,

Lloyd's Register of Shipping,

95, Bothwell Street, Glasgow.

718,

Repairs effected 23/10/44.

Geo. Lockburn

W1645-0104

W1645-0105