



TELEGRAMS
CORRUGATED
MOTHERWELL

SPECIALTY:—CORRUGATED FURNACES.

TELEPHONE
MOTHERWELL
900 (2 LINES)

THE BROOMSIDE BOILER WORKS COY LTD

CAMP ROAD,
MOTHERWELL,
LANARKSHIRE.

23rd. December. 1943.

To Messrs. D. & W. Henderson Ltd.,
Meadowside Works, GLASGOW. W.1.

Ref. Order ex. The Boiler Furnace Co., Ltd. Our Job No. 1761.

Boiler No. M.V. "BRITISH COURAGE".

No.	SECTION	Length	Internal Diameter	Thickness
1	DEIGHTON, WITH STEPHEN GOURLAY, BACK END.	8' 1 1/2"	3' 2"	7/16"

Plates by Colvilles Ltd.,

Nos 1/5416.
has

The Plates have been subjected to mechanical tests and the furnaces passed for workmanship and found satisfactory by Surveyor



W1645-0106

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of it is to be held responsible for any loss or damage to property or for any injury to persons or to the property of others.