

Y A C H T

Chief Ship Surveyor

Received from Chief Ship Surveyor

S NAME

'GIROFLEE'

REPORTS

(Sou.

No.

21209

(Sou.

21210

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Notation of "Rest. Shm. December 49-9"
is assigned.

The SOUTHAMPTON Surveyors report (2,52), the Yacht placed on slipway and the requirements of an Annual Survey complied with.

"A" brackets of heavier scantlings have been fitted at this time to cure leakage in the steering gear compartment (p & s).

The same Surveyors later report the Yacht examined on "hard".

IT IS SUBMITTED the Yacht is eligible to be continued as classed, with record of docking 4,52 and to have Notation of 'AS. Sou. 2,52' assigned as recommended.

4,52 Sou.

AS. Sou. 2,52.



© 2021

Lloyd's Register
Foundation

W1648-0027