

WRECK SECTION

Rpt. 8.

No. 135823

(Received at London Office)

No. 135823

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report... 18 AUG 1952... When handed in at Local Office... Port of LIVERPOOL

No. in Reg. Book 14297 64086 Survey held at LIVERPOOL Date, First Survey 11/8/52 Last Survey 1952

TONNAGE: GROSS 289 UNDER DK 266 NET 115 Built at Selby By whom Cochrane & Sons, Ld. When 1915 12 Owners H.B. Ingram Owners' Address Managers - Port belonging to Fleetwood

Surveyed Afloat or in Dry Dock? Afloat Name of Dock Wyse Dock Destined Voyage Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER * for Special Survey Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
*100A1 Stm.	*IMC 8,51
Trawler 8,51	TS CL.8,51
ssCff. 3,47(Dr)	
ssFlt.-8,51	

N.B. All alterations in the existing records should be underlined.

last Report, No. 133990. Port Liv.

Medical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined. Society's Freeboard (if assigned) as painted on Ship and now certified ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Annual examination of Steering gear.

How done Vessel afloat. Steering gear chains, rods, pins, screws and connections opened and cleaned & examined, and all found or placed in a satisfactory condition

Under Vessel afloat - endorsement item not examined at this time.

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Faird or Repaired								
Faird or Repaired in place ...								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
Planking of Decks	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
Fastenings	Rudder	Scuppers	Boats
Side Plating	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
" In way of sidelights	Windlass	Hatches	Condition, how ascertained
Frames	Have pumps been examined and found efficient?	Planking	(State if wedges removed.)
Transverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Equipment letter
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	Anchors, No. of
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Cables (State if now ranged)
Ports	Air and Sounding Pipes	Transoms, Pointers & Crutches	" length mean diamr.
Belsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	(on board.)
Stringers		" " at other places	" Rule length size
Inner Bottom Plating		Stringers, Clamps & Shelves	Chain Locker
Have the Tanks been examined internally?		Salting	Hawsers & Warps
Have the Tanks been tested?		State if examined	Standing and Running Rigging
			Sails

General Observations, Opinion as to Class, Recommendation, &c. : State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This vessel so far as now seen, is in efficient condition and is eligible in my opinion to remain as classed in the Register Book, without fresh record of survey.

Survey Fee (per Section 23)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 23)	£	:	:	10
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	10

26 AUG 1952

Committee's Minute LIVERPOOL Character Assigned As now (with endorsement) B.S. 8:52. Surveyor to Lloyd's Register of Shipping. Lloyd's Register Foundation. W1649-0044