

12 JUL 1944

at to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "EMPIRE BITTERN"

REPORT Liv. No. 12124

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Docking

When due.....

Subject to indented stem plate (s.s.) and indented sheerstrake plating etc. (p.s.a) being permanently repaired and to the starboard hawsepipe being renewed at the first convenient opportunity.

Wals  
10.7.44

This vessel is excluded from deeper loading.



© 2019

Lloyd's Register  
Foundation

W165-0015