

When held, must be reported in detail and variation in the form of the Survey. The class is subject to the electric welding repair in the port wing furnace of the centre boiler being examined at the next Survey.

2 E

Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

19 JAN 1949

E "SAN ZOTICO"

Rpt..... Bom..... No. 8909

The Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

Agreement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to set out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points noted in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

~~COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No.~~

This Survey, due 9.48 now held minor ~~partly~~ held now -
ated,--and the following repairs carried out (due to wear & tear):-

S.R.L.:- Electric welding repair to port wing furnace of the centre boiler examined and the Surveyor states this item need not remain a condition of class.

Docking.

A General Examination has been held on the machinery for maintenance of class.

It is submitted the vessel is eligible to remain as classed, with

on of BS 11.48 as recommended.

"Examined 11.48" (12 months),

Without special conditions.



© 2019

World's Register
Foundation

18. 1. 49.

W1654-0019

and found or placed in good condition.