

COPY.

Lloyd's Register of Shipping.



Port Hong Kong

5th. March 1938.

This is to Certify that I have

Surveyed the Twin S.S. "EMPRESS OF CANADA" of London,

21517 Gross Tons, No.24415 in the Register Book, for Condition,

Completion of S.S.2nd.No.1 and Renewal of Freeboard.

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs

recommended by me have been completed to my satisfaction, and that I have **Recommended** that she be continued as classed

with fresh record of survey 3-38. and the notation of

S.S.2nd.No.1-3,38. Subject to 15 fathoms chain cable being

repaired, retested and replaced on board.

being fit to carry dry and perishable cargo.

J. S. Morrison

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."