

1

FEB 1943

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "ETNA" REPORT N.Yk. No. 43077

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Docking ~~When due~~

Subject to indented shell plates Nos.5,6 & 10 in D strake (s.s.) & 14 frames in way & E.10 (s.s.) being dealt with at the Owners' convenience, to permanent repairs to panting stringers & framing in No.1 hold (p.s.) at the first convenient opportunity.

PLATING to be DRILLED when vessel is 24 years old or at next Special Survey thereafter.

way
2.2.43



© 2019

Lloyd's Register
Foundation

W167-0028