

shaft  If so, state type

Length of Bearing in **Stern Bush** next to and s

Engine  
Boiler

No. 178778

Made by

Ruston & Hornsby

For

Messrs Winton Tjenford Scheerdaam Holland 659

M.S. "EULIMA"

Survey Report No. 19812

It is submitted that a copy of this Report be  
forwarded to the Rot. Surveyors for their  
~~returned~~ guidance and for completion.

Copy of Rpt  
Sent Rot. 2018.

Ym

Date

17.9.36 © 2020

1m,6,36.

Write Rot



Lloyd's Register  
Foundation

W168-070

Are all Pipes, Cocks, Valves, and Pumps in connection with the machinery and all boiler mountings accessible at all times

Is the arrangement of valves and their connections such as to prevent the possibility of water passing from the sea or from water tanks into the car