

SWAN, HUNTER, & WIGHAM RICHARDSON, LIMITED.

Ship, Engine, Boiler & Floating Dock Builders & Repairers,

WALLSEND-ON-TYNE.

London office, 21, Russell Square, W.C.1.




References Ours 6W.LC.  
Yours

The Secretary,  
Lloyd's Register of Shipping,  
71 Fenchurch Street,  
LONDON E.C.3.

6th January, 1939.  
Friday.

*3 plan*



Dear Sir,

NO. 1567 SHIP.

We have pleasure in enclosing herewith, in triplicate, print showing modified arrangement of Stiffening under Pillar Foot at frame 33, and shall be glad to have your early approval of same.

Yours faithfully,

SWAN, HUNTER, & WIGHAM RICHARDSON, LTD.

L.C. Mac.  
S. J. Lefatue.  
Ved. 8. J. 20.  
TCL. 8. J. 20.


Modified arrangement of stiffening under pillar foot at frame 33.

Message: Swan, Hunter & Wigham Richardson, Ltd.

*1. D. B. Ocker*

NAVAL ARCHITECT

ENCLOSURES.



© 2019

Lloyd's Register  
Foundation

W174-0214

Telephone: WALLSEND 63121.

Telegraphic address: SWANHUNTER, WALLSEND.

All offers are subject to our usual strike, accident and guarantee clauses and to the other conditions in our printed form of contract.

Referred to the Chief Ship Surveyor

-7 JAN 1939

REQUESTING EARLY REPLY.

Submitted for

approval


as

amended  
9/1/39.

Messrs. Swan, Hunter & Wigham Richardson's No. 1567.

Modified arrangement of stiffening under pillar foot  
at frame 33.

Ltr. 6. 1. 39.  
Asd. 9. 1. 39.  
2 plans 1 retained.  
P.C. Nwc.



© 2019

Lloyd's Register  
Foundation