



© 2021

Lloyd's Register  
Foundation

"HERTFORD."

Sud 18, 671.

Transferring the vertical channels, used as "strongbacks", to inside the vessel (after hold was discharged) to act as frames. On completion of this work the upper portion of hole was plated over with channels.

No. 5

Close-up showing numbers five and eight vertical stiffeners in the second position.

Lloyd's Register  
Foundation

W176-0112