

COPY.

15 FEB 1934

# Lloyd's Register of Shipping.

C.2642.



Port GRIMSBY.

14th February, 1934.

**This is to Certify** that

C. H. L. PILDITCH,

the undersigned Surveyor to this Society did at the request of Messrs Ruston & Hornsby, Ltd., attend at their works at Lincoln on the 4th September, 1933 and subsequent dates, for the purpose of inspecting Four Auxiliary Oil Engines Nos. 170053, 170054, 170055 and 170056, Mark 5 VORZ, each of 150 Brake Horse Power and intended for fitting on board the M.V. "INCOMATI" (Messrs Workman Clark & Co., Ltd's Yard No. 532.

These engines have been built under special survey and in accordance with the Rules of, and plans as approved by, this Society, ~~the engines have been built and tested throughout their construction and the materials and workmanship found satisfactory.~~

Running tests were carried out in Messrs Ruston & Hornsby Ltd's works under full load driving generators direct.

After completion of running trials, the main working parts of each engine were opened out for inspection and found satisfactory.

For purpose of identification the engines are stamped as follows:-

<u>Engine No.</u>	<u>Engine No.</u>	<u>Engine No.</u>	<u>Engine No.</u>
<u>170053</u>	<u>170054</u>	<u>170055</u>	<u>170056</u>
LLOYD'S	LLOYD'S	LLOYD'S	LLOYD'S
3190 A	3190 D	3190 B	3190 C
4.12.33	7.12.33	2.1.34	2.1.34
CRAMP	CRAMP	CRAMP	CRAMP
LLOYD'S	LLOYD'S	LLOYD'S	LLOYD'S
TEST	TEST	TEST	TEST
50 lbs.	50 lbs.	50 lbs.	50 lbs.
7.12.33	7.12.33	2.1.34	2.1.34
CRAMP	CRAMP	CRAMP	CRAMP

*C. H. L. Pilditch.*  
Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:- While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for accuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Committee or any Member thereof, or Surveyors, or other Officers or Agents of the Society."