

1

Free paid

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Single Sc.Steamer "IRON KNIGHT"

Report

Grk.

No. 20447

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

FIRST ENTRY

When due

100A1 "With Freeboard"

1 Dk. and Shelter Dk. "Longitudinal framing at bottom, decks and in cantilever side tanks"

Cell.DB. 338' 1394t, DTr 14' 310t, Topside tanks 250' 1042t, FPT 181t
APT 93t.

FK, 7BH (Coll.BH to Shelter dk. 6BH to 2nd Dk.) pt.cem., Lloyd's A & CP.

F 40'

Machy. aft.

O.L.419'

The Certificate of Classification to be endorsed "*Oargo battens not fitted*" and the same notation to be printed in the Register Book



2019
28-10-27

Lloyd's Register
Foundation

W180-0235