

COPY.

# Lloyd's Register of Shipping.



Port Galveston, Texas.

April 20th, 1942.

**This is to Certify** *that I have*

*Surveyed the* <sup>Donkey Part</sup> *Boilers and Machinery of the* Steel Twin Screw M/T "J. A. HOPPETT, JR", 9788 tons gross of Wilmington, Del. at Todd Galveston Dry Docks, Inc., from the 16th March to 11th April, 1942, for Docking Survey, Annual Donkey boiler Survey, part continuous Survey of oil engines, machinery repairs, etc.

*and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have*

**Recommended** *that the record of* DBS - 4,42 now, end +LMC, CS  
*(with date)*

*be made in the Register Book in the case of this vessel when*  
<sup>continuous</sup>  
*the survey has been completed.*

Parts now examined: (numbered from forward)  
Port Main Engine: connections & fastenings.  
Nos. 1, 2, 4 cylinder, liner, piston, rod, valves, gears, cover, top ends & crosshead bearings, guides & shoes.  
Thrust shaft & bearings.  
Starboard Main Engine: Nos. 1, 3, 4 cylinder, liner, piston, rod, valves, gears, cover, top ends & crosshead bearings guides & shoes.  
Thrust shaft & bearings.  
The scavenge pump cylinder, piston & all valves.  
All found or now placed in order.  
Also Donkey boilers surveyed.

*M Dickson*

**Engineer Surveyor to Lloyd's Register.**

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

© 2021  
Lloyd's Register  
Foundation  
W181-0130