

1

Sent to Chief Surveyors.....


Received from Chief Surveyors.....

VESSEL'S NAME JAGERSFONTEIN REPORT Gal. No. 4288For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DOCKING. When due

Subject to permanent repairs to
indented top side shell plating etc. (s.s.amids.) in
way of fuel oil bunker (col.dmg.) at a convenient
opportunity. ✓



© 2019

Lloyd's Register
Foundation

Before confirmation of above Syd. Rpt. awaited.

W182-0016