

'aaparen'

Memorandum.

The two cylinder auxiliary engine, with generator, has now been taken ashore & replaced by a new 4 cylinder auxiliary engine - see report 46 attached to Gothenburg report No. 9929 on the machinery of this vessel.

JTM.
6/6/35.



© 2020

Lloyd's Register
Foundation

W183-0020

their fittings examined.