

Chief Surveyors

Received from Chief Surveyors

EL'S NAME "KING GRUFFYDD"

Report

Liv.

No. 118973

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

(2nd No. 2 SURVEY PARTLY HELD.) DAMAGE & FURTHER GEN.

due 8.39

When proposed to be completed "EXAMINED 1.43" - 12 MONTHS

EXAM.


on of Survey held, &c. The greater part.

TO COMPLETE THE S.S:- Examination of Nos. 2, 3 & 4 D.B. tanks, dry tank, bottom of main bunker and tank top in way to be examined and tested and A.P. tanks to be tested.

Subject to permanent repairs to indented shell plates Nos. 3 & 4 in sheerstrake 1st, 2nd & 3rd strakes below and structure in way (p.s.) at the first convenient opportunity and to inner frame of windlass (s.s.) being renewed at the earliest opportunity.

(Docking date)
1.43

"Examined 1.43"



© 2021

Lloyd's Register
Foundation

W185-0122