


W/18P-0003

S/S "LLANCARVAN."

BREAK OCCURRED
THROUGH CENTRE OF
BOLT HOLES.

UNDERPALM BROKE IN SAME
POSITION.



These are the only details I have, the material having
been disposed of when the clearing letter arrived.

W/18P-0004