

Our Ref: 6360/LM.

(Received at London Office.....12 DEC 1934.....19...)

No. 6 Sets. Place Trafford Park. Date 12.10.34. 19

We request that the Committee of Lloyd's Register will instruct  
the Society's Surveyors to inspect superheaters for Messrs. J. Dickinson  
Sons Ltd., Contract Nos. 271/2.

We undertake to arrange for every facility to be given to the  
surveyors to carry out the duty in question, and we agree to pay the fees  
for the Surveyors' services, in addition to the actual travelling and other  
expenses incurred by the Surveyors in connexion therewith.

This request is made upon the terms of the Rules and Regulations  
of Lloyd's Register of Shipping, which provide that:—

While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be  
understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy  
in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the  
Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.

Hall  
ByThe Superheater Co. Ltd.,  
Trafford Park,  
Manchester. 17.

To the Secretary,

Lloyd's Register of Shipping,

71 Fenchurch Street, London. E.C.3.

© 2020

Lloyd's Register  
Foundation

W189-0170