

Chief Surveyors _____

Received from Chief Surveyors _____

L'S NAME Stl & M/V MACDHUI Report Stl No. 57300**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/93.)


of Survey 1st Entry When due Revised Rule Rule

✠ 100 A.I. (Steel) With Freeboard.

3 D^{ns} (Stl Weather D^k Leak-s)

Cell D.B. 277' 680t, D.T. a 15' 105t, F.P.T. 76t, A.P.T. 56t

F.K. 7 B.H. (Coll B.H. to weather D^k, 6 B.H. to 2nd D^k) pt cm, Clyde ACF.
F 34'


 The Surveyors should be requested to state which of the 3 side
 strakes of shell plating is ~~not~~ ^{is} in thickness.

 Lloyd's Register
 Foundation

W192-0326