



LLOYD'S REGISTER.
LONDON.

3, Steinhoeft,

Hamburg, 2nd April 1922

5 APR 1922

RECD

ANS

re Report # MELISKERK 14902

The length of the Chain Cable onboard is as given in the second page of my report and not as given in the summary viz 563.11 Metres or 308 fathoms of 60 mm Stud Chain cable that the steel wire (for stream chain) tow line and all Hawsers onboard are much in excess of the Rule requirements the Chain locker in fore peak is fitted with a hand pump

This vessel was handed over to the Allies without hand pumps or substitute for same in the form of hand fly wheel pump connected to the hold bilge suctions.

It would perhaps be best to inquire through the Dutch Surveyors respecting the Owners being agreeable to fit hand pumps in holds as required by the Rules should this be required in future.

The Secretary
L O N D O N
XXXXXXXXXXXXXXXXXXXX

I am, Dear Sir

Yours faithfully

Geo. Dykes

© 2019

Lloyd's Register

W195-0053

