

Less Crew Space  
Less above Crown of  
Engine Room

245.14

Depth "d," at middle of length (See Secs. 2 & 15) ....

Proportions—Depths to Length—Upper Deck Beam at }

12.94

Managers  
(Where necessary to be  
Residence

W196-0353

COPY FOR LONDON OFFICE.

# Lloyd's Register of Shipping.

Port

NEWCASTLE-on-TYNE,

12th January, 1922.

This is to Certify that I have

Steel Screw Steamer "OLIVIA" registered to Tonsberg,

Class No. 38420 in the Register Book Supplement

shall

have transmitted to the Committee of Lloyd's

Shipping, London, a Report, stating that all repairs

by me have been completed to my satisfaction, and

Recommended that she be classed as 100 A.1

in the Register Book.


carry

R. Langlands.

Surveyor to Lloyd's Register.

upon the terms of the Rules and Regulations of the Society, which provide that :—

their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or for any error of its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of the Surveyors, or other Officers or Agents of the Society."



© 2020

Lloyd's Register  
Foundation

Angle, Bulb Angle,  
Angles on upper edge  
Spacing

10 3 1/2 58 10 3 1/2 56

and thickness.