

3m, 8.17.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Ste of Montevideo Rpt. Appl No. 15426

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

It is submitted before this case receives the consideration of the Committee the Superintendent of the Metherton Proving House should be requested to forward a copy of the particulars contained in the Bower anchor certificate No 76552.

L. Metherton 12/12/17

[Signature] 10.12.17



© 2020

Lloyd's Register Foundation

BE	Top Deck, angle, bulb angle, ...	12	5	12	12	5	12
	Top Bulb, or Channel		✓			✓	
	Angles on upper edge						

BRIDGE DECK STRINGER PLATE, br'dth & thickness	45	46
" Angle on ditto	4 1/2 x 4 1/2	50

with
of B
U
1, 4
ches:
cing in
hip.
Inches
in Ship
50
42
2
4
34
14
16
4
6
6
7
5
46
50