

No. 25369

of writing Report 2nd August 1913. When handed in at Local Office 2nd August 1913. Port of SUNDERLAND

Search on the ~~Wood~~, ~~Iron~~ or Steel *S/S "Nestor"*

TONNAGE:— Built at *Alloa* By whom *Mackay Bros.* When *1912.*

ROSS 1420 Owners Dampfschiffahrts Ges Neptun Port belonging to Bremen

Owners' Address ✓
(if not already recorded in Appendix to Register Book).

Surveyed Afloat on	NAME OF DOCK	Name of Dock	Destined Voyage
		River Wear	Antwerp

B = *Call* *D* *Bor* *D* *Ba* *feet*; *uE* & *B* *feet*; *f* *feet*;
city *tons. FPT* *tons*; *APT* *tons*; *MT* *feet* *tons*.
 Particulars of Classification (which must be inserted
precisely as in Register Book & Supplements).

10. If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, the inner bottom plating, especially in the boiler space.

Report, No. _____ Port _____

Repairs, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and repairs detailed in the body of the report, should be summarised in the form shown below. Whenever the Anchors or Chains is reported, the particulars should be clearly stated in the space provided on this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as }
painted on Ship and now verified }ft.....ins.

Was a damage report made by anyone else? If so, by whom?

EXAMINATION AS PER RULE, FOR Completion of first entry
done, Downston & hand pump to fore peak tried & found Satisfactory,
Engine & boiler casings fitted and riveted
Hold Ventilators fitted
Pillars in engine & boiler space fitted
Tunnel top riveted and holed

DAMAGE REPAIRS :—	Plates.	Frames.	E. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
				<input checked="" type="checkbox"/>				
Paired or Repaired								
aired in place								

ON OF THE

Survey

Stringers	Dblng. Plates under Sounding Pipes.....	Copper, or Y.M. of Wood Vessels..... <i>(State if on Felt.)</i>
Inner Bottom Plating.....	Engine Room Skylights.....	When put on, Month Year
State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.....	Boats.....
State if Tanks now tested.....	Scupperns.....	Masts, Yards, &c.....
Bulkheads	Cargo Hatchways	Condition, how ascertained..... <i>(State if wedges removed)</i>
Ceiling..... <u>Confined</u>	Hatches..... <u>to above</u>	Sails.....
Cement or Asphalt	Planking	Equipment letter
<i>(State which.)</i>	of Wood Vessels.....	Anchors, No. of
Rudder.....	Caulking	Cables <i>(State if now ranged)</i>
Steering gear and its connections.....	Treenails	" length size
Windlass.....	Breasthooks & Stemson	" <i>(on board)</i>
Have Pumps now been examined and found effi- cient?	Transoms, Pointers, & Crutches ditto.....	" Rule length size
Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto.....	<i>(per Table 30 or 31)</i>
Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto.....	Hawser & Warps.....
	Stringers, Clamps & Shelves	Standing & Running Rigging.....
	Salting	
	<i>(State if examined.)</i>	

Observations, Opinion as to Class, Recommendation, &c.:—

clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this for example:—".....to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of or "to remain as classed and to have record of survey, 1.09, and the notations of *ss No. 1-09 and ptND09, &c.*"

foregoing work has been satisfactorily completed, and so
as regards same, vessel is eligible in my opinion to
the class contemplated by 100 A I

Survey Fee (per Section 38)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any)	£	:	:	19.....
(per Sec. 38)				
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19.....

Surveyor to Lloyd's Register of British & Foreign Shipping

Committee's Minute

Character Assigned

Thos Shaw.

Surveyor to Lloyd's Register of British & Foreign Shipping

AUG 16 1912

the Register of British

LR

© 2020

Lloyd's Register
Foundation

W198-0219

Is Certificate required? If so, to be sent to