

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Steel Ss Ss "CORDENE"*Rpt. *hwc*

No. 78003

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long

Transverse No.

6191

Depth "d"

18.88 to U.D.

Framing: Table No.

2

Description

*Bull angle**22.88 to Q.D.**frames as approved.**2nd*

Longitudinal No.

18071

Proportions

Length =

13.02 to U.D.

Depth =

*11.00 to Q.D.**Deck Sheerstrake as approved.*

This vessel has been built in accordance with the Revised Rules, and the Builders obtained the owners sanction thereto.

This vessel appears to have been built in accordance with the Revised Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100 A.1. (Steel)

1 SK (steel). "well SK"

Cell D.B 24' 549t, M.Ts 14' 205t, F.P.T. 104t, A.P.T. 146t.

F.K, 4 B.H, 1st Com, Lloyd's A & C.P.

P 20', Q 164', F 26'.

The Certificate of Classification, to be endorsed "Cargo battens not fitted," and the same notation to be entered in the Register Book.



© 2010

Lloyd's Register Foundation

W20-0137