



© 2019

Lloyd's Register
Foundation

S. S. "Nellie" Hull report No. 51747.

View of crack in h.p. byl. from inside, showing
studs tapped into cyl. wall at ends of original
fracture.



© 2019

This photograph has been passed
by the approved Authority subject
to the undertaking that it is not
for publication.

Copyright by JOHN DOUGLAS, HULL.

W200-0132