

Brompton Manor

F.E.

Received by Chief Ship Surveyor 1.5.14

Received from Chief Ship Surveyor

VESSEL'S NAME

Steelers 'Aydou'

Rpt.

Two

No.

65962

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

57.58

Depth "d"

16.25

Framing: Table No.

3 page 10

Description

Bulb angle as approved

Longitudinal No.

14682

Proportions

Length

13.07

Depth

Upper Deck Sheerstrake

as per Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\nabla$  100 A-1 (Steel) as recommended

 $\nabla$  100 A-1 (Steel)

1 DK (pl. in - pl. stl.) Well on

WB - Cee &amp; B 41' + 172' 482 L FPT 130 L APT 25

F.R. 4 B.H. Cam: Lops at ep. Pm 61 Q 144 B 41 F 29



© 2020

Moly aft.

Lloyd's Register Foundation

W202-0152