

WOKINGHAM COPY.

LLOYDS REGISTER HALIFAX (N.S)

(22.12.42).

1964 YOUR REPORT 4214 IN VIEW PREVIOUS REPORT CARDIFF AND SUBSEQUENT  
SURVEY LONDON DISCLOSING DEFECTS SHELTER AND TWEEN DECK PLATING AMIDSHIP  
COMMITTEE MUST REQUIRE THESE PARTS SPECIALLY EXAMINED AND DEALT WITH AS  
NECESSARY ON VESSELS ARRIVAL ALSO INVESTIGATE REPORTED LEAKAGE NUMBER FOUR  
HOLD STOP ADVISE OWNERS AGENTS AND ENSURE DEFINITE ARRANGEMENTS

LLOYDS REGISTER



© 2019

Lloyd's Register  
Foundation

W 203-0090