

C 3052

ADVISED TO

*Carroll*

W 203-0210(1/2)

NEWCASTLE-on-TYNE

18th March, 1920.

G. D. AITKEN

the Owners' Representative survey the S.S. "MINNA HORN" 3431 tons gross of London, for the general examination of Bottom. This survey held in continuation of that held at Hull on the 5th instant and subsequently.

The vessel placed in the Mercantile Dry Dock on the 12th March, 1920 bottom, keel and rudder examined cleaned and recoated Rudder found bent, but worked by hand from Port to Starboard and found in working order.


Bent frame and plate on port side No.4 held now temporarily repaired by cutting out frame and landing rivets and re-riveting and caulking same.

In my opinion having read the reports of the condition survey held at Newcastle on the 10th August, 1919 and of the subsequent survey held at Hull as referred to above, so far as could be judged from the inspection made of the parts of the vessel which have been examined at this time, the vessel appears to be in a fit condition to run for a period of six months.

*G. D. Aitken*

Surveyor to Lloyd's Register

W 203-0210(2/2)



© 2020

Lloyd's Register Foundation

C 3053

NEWCASTLE

18th



G. D. AITKEN

the Owners' Representative survey the S.S. "MINNA HORN" 3431 tons gross of London, for the general examination of Bottom. This survey held in continuation of that held at Hull on the 5th instant and subsequently.

The vessel placed in the Mercantile Dry Dock on the 12th March, 1920 bottom, keel and rudder examined cleaned and recoated Rudder found bent, but worked by hand from Port to Starboard and found in working order.

Bent frame and plate on port side No.4 hold now temporarily repaired by cutting out frame and landing rivets and re-riveting and caulking same.

In my opinion having read the reports of the condition survey held at Newcastle on the 10th August, 1919 and of the subsequent survey held at Hull as referred to above, so far as could be judged from the inspection made of the parts of the vessel which have been examined at this time, the vessel appears to be in a fit condition to run for a period of six months.

*G. D. Aitken*

Surveyor to Lloyd's Register

W203-0210(212)



© 2020

Lloyd's Register Foundation